

TOP TEN SCHOOL BUS VIOLATIONS - SCHOOL YEAR 2015			
ID	VIOLATION	OCCURANCE	RANKING
162	ABS light that fails to come on or go off per manufacturer design	155	1
133	Non-manufactured hole larger than a nickel	145	2
261	Exhaust - Leak that results from a crack, rust or broken or missing part	101	3
260	Exhaust - Clamp or bracket NOT resulting in compromised system integrity	82	4
503	Leaking wheel seal	81	5
239	Emergency door seal is missing, loose, or doesn't make contact	64	6
166	Missing or broken brake parts	58	7
233	Cross member, outrigger or other structural support cracked, etc.	58	7
461	Tie Rods/Drag Links - Motion, other than rotational, linkage point LESS than 1/8 inch	53	8
180	No brakes applied upon actuation of the parking brake control(s) - parking brake applied, engine started, shifter in DRIVE, accelerate to 1,100 rpm; parking brake does not hold	52	9
268	Fuel system with evidence of unrepaired leak	52	9
356	(SEAT) Frame broken or loose from floor or sidewall	48	10